

# Android Indoor Station Firmware


## V2.1.28\_210803 Release Note

### (2021-08-05)


Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.28_210803
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

#### Modify

1. Verification code is empty by default.



2. Hik-Connect Service Settings is changed to the place of Settings → Advanced Settings → Configuration → System Maintenance.



3. Fixed some bugs.

## Android Indoor Station Firmware V2.1.22\_210616 Release Note (2021-06-16)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.22_210616
iVMS-4200 Version	Latest baseline
Hik-Connect APP	Latest baseline

### Modify

1. Optimize the compatibility with door station in protocol 1.0 firmware.
2. Solved the problem that the custom ringtone did not take effect after restarting.

## Android Indoor Station Firmware V2.1.22\_210525 Release Note (2021-06-03)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.16_210316
iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220

### New Function

1. On the basis of supporting English, French, Spanish, German, Italian, newly added

multi-language Polish, Portuguese (Brazil), Russian, Turkish, Hungarian, Dutch, Romanian, Czech, Bulgarian, Ukrainian.

2. Add Hik-Connect Service Settings in Wizard.

## Wizard-Hik-Connect Service Settings 4/5

 Enable Hik-Connect Service

LBS Server litedev.hik-connect.com

Verification Code

Previous

Next

Skip

### Modify

1. Hik-Connect service is disabled by default for privacy protection and add Enable Switch for verification code display in Hik-Connect Server Settings.



## Hik-Connect Server Settings

 Cloud Service

LBS litedev.hik-connectru.com

Verification Code

Hik-Connect Server Status Disconnected



< Hik-Connect Server Settings

Cloud Service

LBS litedev.hik-connectru.com

Verification Code 7a

Hik-Connect Server Status Disconnected



## Android Indoor Station Firmware V2.1.16\_210316 Release Note (2021-03-18)

Device Model	DS-KH9310-WTE1, DS-KH9510-WTE1
Firmware Version	Android Indoor Station : V2.1.16_210316
iVMS-4200 Version	3.4.0.10 Build201214
Hik-Connect APP	4.11.0.927220

### New Function

1. Repair the custom ringtone failure after restart.

### Modify